Huber Technology (Pty) Ltd, South Africa



Home ■ HUBER Report ■ Screens ■ Pulborough STW Inlet Screen Upgrade - A Wastewater Case Study

# Pulborough STW Inlet Screen Upgrade - A Wastewater Case Study



Huber Technology completed the inlet screen upgrade at Pulborough STW, installing two HUBER Micro Strainer ROTAMAT® Ro9 / 700's on an elevated inlet works.

### **Project profile**

Working with BTU, Southern Water's small projects delivery team, we looked at various options to replace the old worn out 25-mm Parkwood bar screen and screenings dewaterer. The P.E. for Pulborough was 8,352 and the consented FFT 62 l/s. Flows from the terminal pump station had been recorded up to 160 l/s and the existing screens were allowing unscreened influent into the balance to the storm tanks and the rags and other large items were blocking downstream pumps.

# **HUBER Technology supplied**

- 2x HUBER Micro Strainer ROTAMAT® Ro9 / 700 / 6 combined screens
- Control panels
- M&E installation

## Objective and solution

The maximum size Ro9 / 700 was agreed and fitted to meet the maximum inflow of 160 l/s. It was also decided to fit two screens and remove the existing bypass bar screen.

"Working with BTU to delivery this project within budget and on time was a challenge for everyone. But, with good communication



17 Apr 2024 15:23:57 3/5



17 Apr 2024 15:23:57 4/5



between BTU, Southern Water and Huber, the end result was a great success" commented Adrian Heneghan, HUBER Area Manager.

Ricky Corkett, Southern Water site operator also commented that he was, "More than happy with the screens. Now I have time to work on other parts of the site and not have to worry about lifting and clearing pumps".

17 Apr 2024 15:23:57 5/5

For more information please contact Adrian Heneghan at Huber technology UK, +44 7540 667094, athhuber.couk.

#### **Related Products:**

■ HUBER Micro Strainer ROTAMAT® Ro9

### **Related Solutions:**

■ HUBER Solutions for Mechanical Pre-Treatment

Huber Technology (Pty) Ltd

Company Reg. No.: 1992/006606/07

PO Box 9813 George, 6530 South Africa Phone +27 44 874 4242 Fax +27 44 874 3658 huber@lantic.net http://www.hubersa.com

A member of the HUBER Group